

[illegible]

Law Enforcement and TxDOT Use ONLY. Form CR-3 (Rev. 4/1/2023)		Case ID	TxDOT Crash ID		Page 2 of 2											
DISPOSITION OF INJURED/KILLED	Unit Num.	Prsn. Num.	Taken To		Taken By		Date of Death (MM/DD/YYYY)		Time of Death (24HRMM)							
CHARGES	Unit Num.	Prsn. Num.	Charge						Citation/Reference Num.							
	1	1	DISREGARD TRAFFIC CONTROL DEVICE MC													
DAMAGE	Damaged Property Other Than Vehicles			Owner's Name			Owner's Address									
CMV	Unit Num.	☐ 10,001+ LBS.	☐ Transporting Hazardous Material	☐ 9+ Capacity	CMV Disabling Damage?	☐ Yes ☐ No	30 Veh. Oper.	31 Carrier ID Type	Carrier ID Num.							
	Carrier's Corp. Name			Carrier's Primary Addr.			32 Veh. Type									
	33 Bus Type	☐ RGWW ☐ GVWR	HazMat Released	☐ Yes ☐ No	34 HazMat Class Num.	HazMat ID Num.	34 HazMat Class Num.	HazMat ID Num.	35 Cargo Body Type							
	Unit Num.	☐ RGWW ☐ GVWR	36 Trlr. Type	CMV Disabling Damage?	☐ Yes ☐ No	Unit Num.	☐ RGWW ☐ GVWR	36 Trlr. Type	CMV Disabling Damage?	☐ Yes ☐ No						
	Sequence Of Events	37 Seq. 1	37 Seq. 2	37 Seq. 3	37 Seq. 4	Intermodal Shipping Container Permit	☐ Yes ☐ No	Actual Gross Weight	Total Num. Axles							
FACTORS & CONDITIONS	38 Contributing Factors (Investigator's Opinion)				39 Vehicle Defects (Investigator's Opinion)				Environmental and Roadway Conditions							
	Unit #	Contributing		May Have Contrib.		Contributing		May Have Contrib.		40 Weather Cond.	41 Light Cond.	42 Entering Roads	43 Roadway Type	44 Roadway Alignment	45 Surface Condition	46 Traffic Control
	1	16								1	1	2	3	1	1	3
NARRATIVE AND DIAGRAM	Investigator's Narrative Opinion of What Happened (Attach Additional Sheets if Necessary)										Field Diagram - Not to Scale					
	Unit 2 was traveling southbound 10900 Red Bluff rd. Unit 1 was traveling westbound 9400 Bay Area Blvd. Unit 1 Ran the Red Light and struck Unit 2. Lattitude was 29.602 and Longitude was -95.06.										Indicate North					
INVESTIGATOR	Date Notified (MM/DD/YYYY)				Time Notified (24HRMM)				How Notified							
	02 / 19 / 2024				1 4 4 7				DISPATCH RADIO							
	Date Arrived (MM/DD/YYYY)				Time Arrived (24HRMM)				Report Date (MM/DD/YYYY)							
	02 / 19 / 2024				1 4 5 7				02 / 19 / 2024							
	Date Roadway Cleared (MM/DD/YYYY)				Time Roadway Cleared (24HRMM)				Date Scene Cleared (MM/DD/YYYY)				Time Scene Cleared (24HRMM)			
02 / 19 / 2024				1 5 4 0				02 / 19 / 2024				1 5 4 0				
Investigation Complete ☒ Yes ☐ No		Investigator Name (Printed)						ID Num.								
		BARRIONUEVO, ROBERTO						0369								
ORI Num.		Agency						Service/Region/DA								
		PASADENA POLICE DEPARTMENT														