

/VEHICLE, DRIVER & PERSONS

Law Enforcement and TxDOT Use ONLY. Form CR-3 (Rev. 4/1/2023)										Case ID		TxDOT Crash ID		Page 2 of 2									
DISPOSITION OF INJURED/KILLED	Unit Num.	Prsn. Num.	Taken To				Taken By				Date of Death (MM/DD/YYYY)				Time of Death (24HRMM)								
	2	1	Refused				Self																
CHARGES	Unit Num.	Prsn. Num.	Charge										Citation/Reference Num.										
	1	1	FTWTROW																				
	2	1																					
DAMAGE	Damaged Property Other Than Vehicles						Owner's Name						Owner's Address										
CMV	Unit Num.	☐ 10,001+ LBS.	☐ Transporting Hazardous Material		☐ 9+ Capacity		CMV Disabling Damage?		☐ Yes ☐ No	30 Veh. Oper.		31 Carrier ID Type		Carrier ID Num.									
	Carrier's Corp. Name				Carrier's Primary Addr.												32 Veh. Type						
	33 Bus Type		☐ RGWW ☐ GVWR		HazMat Released		☐ Yes ☐ No	34 HazMat Class Num.		HazMat ID Num.		34 HazMat Class Num.		HazMat ID Num.		35 Cargo Body Type							
	Unit Num.		☐ RGWW ☐ GVWR		36 Trlr. Type		CMV Disabling Damage?		☐ Yes ☐ No	Unit Num.		☐ RGWW ☐ GVWR		36 Trlr. Type		CMV Disabling Damage? ☐ Yes ☐ No							
	Sequence Of Events		37 Seq. 1		37 Seq. 2		37 Seq. 3		37 Seq. 4		Intermodal Shipping Container Permit		☐ Yes ☐ No	Actual Gross Weight		Total Num. Axles							
FACTORS & CONDITIONS	38 Contributing Factors (Investigator's Opinion)						39 Vehicle Defects (Investigator's Opinion)						Environmental and Roadway Conditions										
	Unit #	Contributing			May Have Contrib.		Contributing			May Have Contrib.		40 Weather Cond.	41 Light Cond.	42 Entering Roads	43 Roadway Type	44 Roadway Alignment	45 Surface Condition	46 Traffic Control					
	1	35										1	1	2	4	1	1	17					
NARRATIVE AND DIAGRAM	Investigator's Narrative Opinion of What Happened (Attach Additional Sheets if Necessary)										Field Diagram - Not to Scale												
	The 7200 block of Gateway East is a one-way marked roadway with three lanes that travels east. The 1900 block of Roswell is a two-way marked roadway that travels north and south. Unit 2 was traveling on lane #1 of 7200 Gateway East. Unit 1 was traveling north on 1900 Roswell. Unit 1 failed to yield the right of way when making a right turn from 1900 Roswell to 7200 Gateway East, colliding with Unit 2. Unit 2 operator complained of pain to the left side of his body, but refused transport to a medical facility. Both vehicles were privately towed. There were no witnesses reported.										Indicate North 7200 GATEWAY EAST UNIT 2 UNIT 1 1900 ROSWELL Not To Scale N												
INVESTIGATOR	Date Notified (MM/DD/YYYY)						Time Notified (24HRMM)				How Notified												
	1 0 / 2 7 / 2 0 2 3						1 4 5 4				Dispatched												
	Date Arrived (MM/DD/YYYY)						Time Arrived (24HRMM)				Report Date (MM/DD/YYYY)												
	1 0 / 2 7 / 2 0 2 3						1 5 1 3				1 0 / 2 7 / 2 0 2 3												
	Date Roadway Cleared (MM/DD/YYYY)						Time Roadway Cleared (24HRMM)				Date Scene Cleared (MM/DD/YYYY)				Time Scene Cleared (24HRMM)								
1 0 / 2 7 / 2 0 2 3						1 5 1 3				1 0 / 2 7 / 2 0 2 3				1 6 0 0									
Investigation Complete		☒ Yes ☐ No	Investigator Name (Printed)								ID Num.												
			Rodriguez, K.								3225												
ORI Num.		T X 0 7 1 0 2 0 0	*Agency								Service/Region/DA												
			EL PASO POLICE DEPARTMENT								M V												